```
Lynn Hubbard III, SBN 69773
 1
   Scottlynn J Hubbard, IV, SBN 212970
   Law Offices of Lynn Hubbard
    12 Williamsburg Lane
   Chico, Ca. 95926
 3
                (530) 895-3252
   Telephone:
   Facsimile:
                 (530) 894-8244
 4
   Attorneys for Plaintiff
 5
 6
 7
 8
 9
                       United States District Court
                      Eastern District Of California
10
11
                                        Case No. Civ.S-04-0003 FCD PAN
    Jerry Doran,
12
              Plaintiff,
                                        Order
13
    VS.
14
    JJ Motels dba Super 8 Motel;
15
   and DOES 1 through 10,
16
              Defendant.
17
         Plaintiff Jerry Doran filed this action against defendant JJ
18
19
   Motel for violating Title III of the Americans with Disabilities
20
   Act ("ADA") and related state disabled access laws at the Super 8
   Motel located in Auburn, California ("the Motel"). He avers that
21
   defendant denied him full and equal enjoyment and use of the
22
23
   motel, and failed to remove barriers that violate federal
24
   disability access standards, viz., the Americans with
25
   Disabilities Act Accessibility Guidelines ("ADAAG") codified at
   Appendix A of 28 C.F.R. Part 36, and Title 24 of the California
26
27
   Building Code ("CBC").
28
   ///
```

## 

By way of a motion for summary judgment, Doran sought damages pursuant to the Unruh Civil Rights Act ("Unruh Act"), Calif. Civil Code § 52(a), and injunctive relief pursuant to the ADA, 42 U.S.C. § 12188(a)(2). Because defendant does not oppose the motion (see Non-Opp'n, filed May 13, 2005), the court orders the following:

#### Injunctive relief:

Defendant will remediate the following barriers <u>within one</u> <u>year</u> of the issuance of this order:

- 1. The Motel's (outside) fire extinguishers may protrude no more than four inches into the path of travel, and must comply with ADAAG § 4.4.1 and CBC § 1133B.8.6.1.
- 2. The Motel's walks and pedestrian ways must have a grate with less than a 1/2 inch space, and comply with ADAAG § 4.5.4 and CBC § 1133B.7.2.
- 3. The Motel's accessible route of travel must have a ramp over abrupt changes, and comply with ADAAG ' 4.5.2 and CBC ' 1133B.7.4.
- 4. The Motel=s sidewalk (at the driveway) and outside hallway/walkway path of travel must have a cross-slope less than 2%, and comply with CBC § 1133B.7.1.3 and ADAAG § 4.3.7.
- 5. The floor mats at the Motel must be secured to the floor, and comply with CBC  $\S$  1124B.3 and ADAAG  $\S$  4.5.3.
- 6. The Motel's front office must provide an aisle of 36 inches in width for a wheelchair to access the vending machine, and comply with ADAAG § 4.3.3 and CBC § 1133B.6.2.
- 7. The Motel's van accessible parking space must have the

## Case 2:04-cv-00003-FCD-CMK Document 26 Filed 05/23/05 Page 3 of 7

- "Van Accessible" sign, and comply with ADAAG  $\S$  4.6.4 and CBC  $\S$  1129B.5.
- 8. The Motel must provide tow-away signage, and comply with Calif. Vehicle Code  $\S$  22511.8(d), CBC  $\S$  1129B.5 and Department of Transportation R 100B.
- 9. The Motel's existing disabled parking stall must be at least 9 feet wide with an access aisle of 5 feet wide and have the words "NO PARKING" painted across the access aisles, and comply with CBC § 1129B.4.
- 10. The Motel's van accessible access aisle must be at least 8-feet wide, and comply with CBC  $\S$  1129B4 and ADAAG  $\S$  4.6.3.
- 11. The ramp adjacent to the Motel's accessible parking must avoid protruding into the unloading area (causing a side slope greater than 2%), and comply with CBC  $\S$  1129B.4.3 and ADAAG  $\S$  4.6.3.
- 12. The Motel's accessible parking spaces, and access aisles must have a 2% (maximum) slope, and comply with CBC § 1129B.4.3 and ADAAG § 4.6.3.
- 13. The Motel must provide a mechanism for gaining entry to the pool (i.e., a pool lift), and comply with CBC  $\S$  1104B.4.3.
- 14. The opening hardware for the Motel's pool gate must be centered between 30 to 44 inches above the floor, and must provide opening hardware on the outside of the gate, and comply with ADAAG § 4.13.9 and CBC §§ 1133B1.1.1.4, 1133B.2.5.2.
- 15. The kick plate for the Motel's pool gate must be a

- 10-inch, smooth and uninterrupted surface, and comply with CBC \$\$ 1133B.1.1.1.4, 1133B.2.6.
- 16. The Motel's outside picnic table must be located on an accessible path of travel that is identified by the International Symbol of Accessibility ("ISA"), and comply with ADAAG §§ 4.30.7, 9.1.1 and CBC §§ 1111B.2, 1117B.5.8.1.
- 17. The Motel's accessible parking stall must have a profile that is 36 inches high by 36 inches wide, and comply with CBC  $\S$  1129B.5(2).
- 18. The doors to the Motel's front office and the night window must display the ISA and comply with CBC  $\S$  1117B.5.8.1 and ADAAG  $\S$  4.30.7.
- 19. The Motel must have door landings that are level, and comply with CBC  $\S$  1133B.2.4.2 and ADAAG  $\S$  4.13.6.
- 20. The Motel's night check-in window must include a level landing, and comply with CBC § 1111B.2 and ADAAG § 9.1.1.
- 21. The Motel must provide accessible rooms in accordance with ADAAG \$\$ 9, 9.1, and 9.2.
- 22. Room number 102 of the Motel must have the minimum strike side distance of 24 inches, and comply with CBC  $\S$  1133B.2.4.3 and ADAAG  $\S$  4.13.6.
- 23. The doors to the Motel's outside restroom and front office must take no more than 5 pounds of pressure to open, and comply with CBC  $\S$  1133B.2.5 and ADAAG  $\S$  4.13.11.
- 24. The Motel's lavatories must be mounted with the rim (or counter edge) no higher than 34 inches above the finished floor; have vertical clearance no less than 29 inches (measured from the bottom of the apron of the lavatory, and

## Case 2:04-cv-00003-FCD-CMK Document 26 Filed 05/23/05 Page 5 of 7

- reduced to 27 inches at a point located 8 inches back from the front edge); be a minimum of 18 inches to the centerline of the fixture (when located adjacent to a sidewall); and comply with CBC § 1115B.2.1.2.1 and ADAAG § 4.19.2.
- 25. The mirrors of room number 102 and the Motel's outside restroom must be mounted less than 40 inches above the finished floor, and comply with CBC  $\S$  1115B.9.1 and ADAAG  $\S$  4.19.6.
- 26. The Motel's outside restroom must have the hot water pipes or the drainpipes insulated under the lavatory, and comply with CBC § 1115B.2.1.2.2 and ADAAG § 4.19.4.
- 27. The Motel's outside restroom must have a paper towel dispenser that protrudes less than 4 inches from the wall, and complies with CBC § 1133B.8.6.1 and ADAAG § 4.4.1.
- 28. The Motel's outside restroom must have a soap dispenser mounted within 40 inches from the finished floor, and comply with CBC § 1115B.9.2 and ADDAG § 4.23.7.
- 29. The toilet tissue dispenser in room number 102 of the Motel must be located on the wall within 12 inches of the front edge of the toilet seat, and comply with CBC § 1115B.9.3.
- 30. The water closet in room number 102 of the Motel must have the requisite 42-inch minimum clear floor space, and comply with ADAAG  $\S$  4.16.2.
- 31. The grab bars in room number 102 of the Motel must be located on one side and the back of the accessible toilet stall or compartment, 33-inches above (and parallel to) the floor, mounted on the side wall a minimum of 52-inches from

the back wall, and comply with CBC § 1115B.8.1 and ADAAG § 4.17.6.

- 32. The water closets in both the outside restroom and room number 102 of the Motel must be centered 18-inches from the wall, and comply with CBC \$ 1115B.7.2 and ADAAG \$ 4.17.3.
- 33. The Motel's outside restroom must provide 12 inch clearance between the wall and the grab bar, and comply with CBC  $\S$  1115B.8.2 and ADAAG  $\S$  4.26.2.
- 34. The height of the Motel's outside restroom water closet must be less than 19-inches, and comply with CBC  $\S$  1115B.2.1 and ADAAG  $\S$  4.16.3.
- 35. The towel and clothes hangers in room number 102 of the Motel must be located no more than 54 inches (side approach) or 48 inches (front approach) above the finished floor, and comply with CBC  $\S$  1125B.3 and ADDAG  $\S$  4.25.3.
- 36. The phone for the Motel's front office must have a 30-inch by 48-inch clear floor space for either a forward or parallel approach, and comply with CBC § 1117B.2.2 and ADAAG § 4.31.2.
- 37. The Motel's front office must have a portion of the counter that is 36 inches wide and 28 to 34 inches high, and comply with CBC \$ 1122B.4 and ADAAG \$ 7.2.
- 38. The Motel must provide at least one roll-in shower, and comply with CBC  $\S$  1111B.4.2 and ADAAG  $\S$  9.1.2.
- 39. Room number 102 of the Motel must provide a 36-inch clear space around the bed, and comply with CBC \$ 1111B.4.3 and ADAAG \$ 9.2.2.
- 40. The table in room number 102 of the Motel must have

# 

knee space of at least 27-inches high, 30-inches wide, and 19-inches deep, and comply with CBC  $\S$  1122B.3 and ADAAG  $\S$  4.32.3.

The court declines to provide explicit instructions on the appropriate means to accomplish this directive, and, instead, leaves "logistical matters" concerning the implementation in the capable hands of Defendant. Fortyune v. Am. Multi-Cinema, Inc., 364 F.3d 1075, 1087 (9th Cir. Cal. 2004).

#### Damages:

Plaintiff is also awarded damages in the amount of \$16,000.

#### IT IS SO ORDERED:

Dated: May 20, 2005

/s/ Frank C. Damrell Jr.
FRANK C. DAMRELL, JR.
UNITED STATES DISTRICT COURT